## Installation equipment and accessories

## Conductor bushing



### 8174/204-4813-33 Art. No. 139324



- · Power supply in Ex d enclosures
- · One to 72 cores are combined in one conductor bushing
- · Versions: Screwable, pluggable
- For voltages up to max. 1000 V
- For conductor cross-sections up to 70 mm<sup>2</sup>

## MY R. STAHL 8174A



The conductor bushings are used to connect the conductors between enclosures with the "flame-proof" and "increased safety" types of protection.

The cores are moulded with high-quality, leakage-current-resistant PU resin, meaning that they are insulated from the enclosure wall.

#### **Technical Data**

Explosion Protection	
Application range (zones)	1, 2
IECEX gas certificate	IECEx PTB 06.0081U
IECEx gas explosion protection	Ex db IIC Gb
IECEX firedamp certificate	IECEx PTB 06.0081U
IECEx firedamp protection	Ex db I Mb
ATEX gas certificate	PTB 01 ATEX 1065 U
ATEX gas explosion protection	€ II 2 G Ex db IIC Gb
ATEX firedamp certificate	PTB 01 ATEX 1065 U
ATEX firedamp protection	□ I M2 Ex db I Mb
Certificates	ATEX (PTB), China (CQST), IECEx (PTB)
Electrical Data	
Rated operational voltage AC	750 V
Rated operational current	4.5 A
Ambient Conditions	
Ambient temperature	-40 °C +110 °C
Mechanical Data	
Socket diameter	ø 41
Ex d conductor length	1300 mm
Ex e conductor length	1300 mm
Min. conductor cross section	0.5 mm <sup>2</sup>
Number of core ends	48
Thread size	M48
Thread pitch	1,5
Cable colour	Black
Weight	1.4 kg
Weight	3.09 lb


# Installation equipment and accessories


## Conductor bushing



## 8174/204-4813-33 Art. No. 139324

### **Technical Drawings – Subject to Alterations**





### **Accessories**

Cheese-head screw	
M4 x 6 Three cheese-head screws are required per stopping plug or threaded piece	109806
Split washer	
M4 Three split washers are required per stopping plug or threaded piece	252066
Stopping plugs	
for sealing unused threaded pieces  Note: Please order cheese-head screws and split washers separately	
Dia. 41 mm, M48 x 1.5	139732
	Art. No.
Note: Please order cheese-head screws and split washers separately	
for pluggable conductor bushings 8174/2 Drilled hole diameter dia. 41 mm Screw-in thread M48 x 1.5	140038
	M4 x 6 Three cheese-head screws are required per stopping plug or threaded piece  M4 Three split washers are required per stopping plug or threaded piece  for sealing unused threaded pieces Note: Please order cheese-head screws and split washers separately  Dia. 41 mm, M48 x 1.5  Note: Please order cheese-head screws and split washers separately for pluggable conductor bushings 8174/2 Drilled hole diameter dia. 41 mm

We reserve the right to make alterations to the technical data, dimensions, weights, designs and products available without notice. The illustrations cannot be considered binding.